



ASIA TEXTILE INSPECTIONS LIMITED

Suite 1601-2 Kowloon Plaza,
485-Castle Peak Road, Kowloon,
HONG KONG
Tel: +852-2724-4786
Fax: +852-2721-5786
info@asiatextileinspections.com
www.asiatextileinspections.com

Date: _____ Report Number: _____ Page 1 of 6

INSPECTION REPORT

Buyer:		PO #				
Agent:		L/C #				
Supplier:						
Manufacturer:						
Product Description: High chair remove table						
Item code	PO qty (pcs)	Presented qty	Finished	Unfinished	Packed	Status
1044804018500	100	100	100%	0%	100	100% packed
Inspection Type Performed: FRI (Final random inspection)			Inspection Date:			
Inspection Location:						

INSPECTION CONCLUSION (In comparison to principal's instruction & reference sample, as available)

	Conform	Not Conform	
Quantities submitted for inspection:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	As per PO Qty
Style, material, color:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	As per instruction
Workmanship appearance/functioning:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	AQL 2.5/4.0 Level I Please refer to 2 for details
Packing:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Please refer to 4.1 for details
Marking/label:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	As per instructions.
Measurements/field tests:	<input type="checkbox"/>	<input type="checkbox"/>	Actual finding 1piece measured

General observation: _____

- Reservation:** 1) Found the printing of blue book is poor and the quality paper of it is thinner and softer than reference sample. At same time found the draft and word printing on both side of the same paper of assembly instruction, While reference only printing on one face. The quality of paper is thinner and softer than reference too.
2) The color of screw is not gold yet , while client advise the supplier to revise it .
3) Back side still not add fasten screw which buyer special requirement it .
4) The content of label stuck on back side missed word " Norma" and "No" at right top of label. Please refer to photos for details.

OVERALL INSPECTION CONCLUSION: **CONFORM** **NOT CONFORM** (Please refer to 2 & 4.1 for details and reservation of Page 1)

Follow up action: (as applicable)

- () Inspection certified will be issued after client's confirmation/ approval for reservations.
 () Additional services: () Loading supervision(After Principle's approval () Stuffing supervision () Testing () others_____

Samples drawn by:

For Lab testing: _____ For record: _____ For Client: _____ Sealed at factory: _____

Or reason for not taking samples: _____



ASIA TEXTILE INSPECTIONS LIMITED

Suite 1601-2 Kowloon Plaza,
 485-Castle Peak Road, Kowloon,
 HONG KONG
 Tel: +852-2724-4786
 Fax: +852-2721-5786
info@asiatextileinspections.com
www.asiatextileinspections.com

Date: _____ Report Number: _____ Page 2 of 6

INSPECTION METHOD APPLIED:

ANSI / ASQC Z1.4-1993, Single sampling plan Or: **AQL 2.5/4.0 LEVEL I**

Acceptable Quality Level(AQL) for: Critical: 0 Major: 0 Minor: 1 Sample size: **5pcs for major and 13 pcs for minor**

Sample Selection formula: No. of Cartons Selected: **13 cartons**

Samples selected from package numbers : **no carton number available**

1. PRODUCT CONFORMITY:

1.1 Style Conformity: yes no no reference sample / specification available

1.2 Material Conformity: yes no no reference sample / specification available

1.3 Color Conformity: yes no no reference sample / specification available

Reference sample provided

From principal from manufacturer
 From supplier not available (explanation if necessary)

2. WORKMANSHIP APPEARANCE / FUNCTION INSPECTION FINDINGS:

Defective samples	Critical	Major	Minor
Crack of wood		01	
Uneven paint			01
Mark of wood		01	
Color mark		01	
Total Defectives :		03	01
Maximum allowed :		0	01

Requested AQL

Critical defective maximum allowed Within AQL Found beyond AQL
 Major defective maximum allowed **0** Within AQL Found **03** beyond AQL
 Minor defective maximum allowed **01** Within AQL Found **01** beyond AQL

Reservation: _____

3. PRODUCT-SPECIFIC CHECKS ON REDUCED SAMPLE SIZE (as applicable for specific product / order)

Size measurement on 1 sub-samples: yes no actual finding



ASIA TEXTILE INSPECTIONS LIMITED

Suite 1601-2 Kowloon Plaza,
 485-Castle Peak Road, Kowloon,
 HONG KONG
 Tel: +852-2724-4786
 Fax: +852-2721-5786
info@asiatextileinspections.com
www.asiatextileinspections.com

Date:

Report Number:

Page 3 of 6

Measurement Point	Size	Ref. Sample	Spec.	Tolerance	Deviation/ Finding	Sample(s)

4. PACKING:

- 4.1. Individual packing Conformity: yes no Different way from client requirement (Please refer to photos)
()
- 4.2. Inner packing conformity: yes no _____ ()
- 4.3. Export packing conformity yes no 2-ply corrugated cardboard export carton sealed by gummed tapes and fasten by metal staples ()
- 4.4. Packing assortment Checked on **13** cartons. **Found correct**

Carton No.	Size/ Style	Color	Deviation(+ / - samples)

5. MARKING / LABEL :

Actual shipping Marks(if shipping marks not provided in advance)
Please see photo report

- 5.1. Bar code conformity yes no stuck on one long side of carton. ()
- 5.2. Shipping mark conformity: yes no Logo stuck on one long side of carton ()
- 5.3. Other marks: yes no stuck on top of carton side. _____ ()
- 5.3.1 Side mark conformity: yes no _____ ()
- 5.3.2 Main label: yes no _____ ()
- 5.3.3 Care label: yes no _____ ()
- 5.3.4 Composition label: yes no _____ ()
- 5.3.5 Size label yes no _____ ()
- 5.3.6 Country origin label: yes no _____ ()
- 5.3.7 Hangtag: yes no blue book ()
- 5.3.8 Polybag printing/ label: yes no _____ ()



ASIA TEXTILE INSPECTIONS LIMITED

Suite 1601-2 Kowloon Plaza,
485-Castle Peak Road, Kowloon,
HONG KONG
Tel: +852-2724-4786
Fax: +852-2721-5786
info@asiatextileinspections.com
www.asiatextileinspections.com

Date: _____ Report Number: _____ Page 4 of 6

5.3.9 Inner box printing / label: yes no _____ ()

5.3.10 Other Label yes no a label stuck on back of chair _____ ()

6.0 INFORMATIVE OBSERVATIONS:
Inspection Environment:

Lighting: Daylight Room lighting Sufficient Insufficient Other : _____
 Inspection place: Factory workshop: Warehouse Others : _____
 Inspection done on: Table Top of cartons Others : on the ground
 Cleanliness: Clean Dirty Others : _____
 Weather condition: Rainy Dry Others : _____

7. LOADING SUPERVISION:

Performed on _____ Schedule for _____ Not required _____

Seal no.: _____

8. ATTACHMENTS: Photo report.

9. Checklist:

2. BABY HIGHCHAIR			
DIMENSIONS FOR CHAIR			
	DISCRIPTION	SPECIFICATION	
2.1	Length (including Leg)	35-Cm	4
2.2	Width (including Leg)	38-Cm	38
2.3	Height		
2.3.1	From leg bottom to seat back rest top	66-Cm	66
2.3.2	From leg bottom to arm rest top	41.5-Cm	42
2.4	Seat	Seat	
2.4.1	Length	29-cm	29
2.4.2	Width	32.5-Cm	32.5
2.4.3	Thickness	1.5-Cm	1.2
2.5	Back rest		
2.5.1	Width	32.5 CMS	32.5
2.5.2	Height	38 CMS	37.5



ASIA TEXTILE INSPECTIONS LIMITED

Suite 1601-2 Kowloon Plaza,
485-Castle Peak Road, Kowloon,
HONG KONG
Tel: +852-2724-4786
Fax: +852-2721-5786
info@asiatextileinspections.com
www.asiatextileinspections.com

Date:

Report Number:

Page 5 of 6

2.5.3	Thickness	1.5 CMS	1.2
2.6	Arm rest/leg supports		
2.6.1	Width	2.5 CMS	2.5
2.6.2	Thickness	2.5 CMS	2.5
2.7	Arm rest vertical support Radius	2.5CMS	2.2
2.8	Front leg support Radius	2.5 CMS	2.5
	Chair's Base		
2.9	Length	48 CMS	48.5
2.10	Width	44 CMS	44.5
2.11	Height	56 CMS	55.5
2.12	Top Arm		
2.12.1	Width	2.5 CMS	2.5
2.12.2	Thickness	2.5 CMS	2.5
2.13	Top arm support Radius	2.5 CMS	2.2
2.14	Middle support		
2.14.1	Leg support (Length wise) width	2.5 CMS	2.5
2.14.2	Leg support (Length wise) thickness	2.5 CMS	2.5
2.15	Leg support (Width wise) width	6 CMS	6
2.15.1	Leg support (Width wise) Thickness	2.5 CMS	2.5
	Dimension for fixed/complete high chair		
2.16	Chair table top Length	45 CMS	45
2.16.1	Chair table top Width	29 CMS	28.5



ASIA TEXTILE INSPECTIONS LIMITED

Suite 1601-2 Kowloon Plaza,
485-Castle Peak Road, Kowloon,
HONG KONG
Tel: +852-2724-4786
Fax: +852-2721-5786
info@asiatextileinspections.com
www.asiatextileinspections.com

Date:

Report Number:

Page 6 of 6

2.17	Total height including seat back rest	97 CMS	97
2.18	Height at front side from base to chair table top	75.5 CMS	76
2.19	Height at front side from base to chair seat	60 CMS	59