

Suite 1601-2 Kowloon Plaza, 485-Castle Peak Road, Kowloon, HONG KONG Tel: +852-2724-4786 Fax: +852-2721-5786 info@asiatextileinspections.com www.asiatextileinspections.com

| Date: Report Number:                |                      |         |              |      |                  |                       |                        | Page 1 of 5 |  |  |
|-------------------------------------|----------------------|---------|--------------|------|------------------|-----------------------|------------------------|-------------|--|--|
|                                     |                      |         | INSI         | PE   | CTION REP        | PORT                  |                        |             |  |  |
| Buyer: FPO # 001460                 |                      |         |              |      |                  |                       |                        |             |  |  |
| Agent:                              |                      |         |              |      | L/C #            |                       |                        |             |  |  |
| Supplier:                           |                      |         |              |      |                  |                       |                        |             |  |  |
| Manufacturer:                       |                      |         |              |      |                  |                       |                        |             |  |  |
| Product Descrip                     | tion: Men's genu     |         |              | et   |                  | -                     |                        |             |  |  |
| Style No.                           | PO qty(PCS)          | Preser  | nted qty     | Fi   | nished           | Unfinished            | Packed(carton)         | Status      |  |  |
| MAPLE                               | 287                  | 300     |              |      | 0%               | 0%                    | 24                     | 100% packed |  |  |
| VUITTON                             | 140                  | 146     |              | 10   | 0%               | 0%                    | 11                     | 100% packed |  |  |
| AVENUE                              | 852                  | 847     |              | 10   | 0%               | 0%                    | 22                     | 100% packed |  |  |
| SHERBA                              | 3584                 | 3627    |              | 10   | 0%               | 0%                    | 95                     | 100% packed |  |  |
| HUDSON                              | 366                  | 383     |              | 84   | 1%               | 16%                   | 7                      | 78% packed  |  |  |
| CUTTER                              | 970                  | 945     |              | 85   | 5%               | 15%                   | 16                     | 80% packed  |  |  |
| TOTAL                               | 6199                 | 6248    |              |      |                  |                       | 175                    |             |  |  |
|                                     | Performed: FRI       |         |              |      |                  | Inspection D          | ate:                   |             |  |  |
| Inspection Locat                    | tion: Room 2711      | No.12 V | Vest Lake    | e A۱ | /enue Hangzł     | nou, China            |                        |             |  |  |
| <b>INSPECTION CC</b>                | NCLUSION (In         | compari | son to pri   | ncip | oal's instructio | n & reference         | sample, as available   | e)          |  |  |
|                                     |                      |         | Conforn      | n    | Not              |                       |                        |             |  |  |
|                                     |                      |         |              |      | Conform          |                       |                        |             |  |  |
| Quantities subm                     | itted for inspection | on:     | $\checkmark$ |      |                  | Presented Q           | ty is plus 49 pcs that | an PO Qty   |  |  |
| Style, material, color:             |                      |         |              |      |                  | to photos for details |                        |             |  |  |
| Workmanship appearance/functioning: |                      |         |              |      | $\checkmark$     | AQL 2.5/4.0           | Level II & reservation | ons         |  |  |
| Packing:                            |                      |         | $\checkmark$ |      |                  | As per instru         | ctions (provided by    | supplier)   |  |  |
| Marking/label:                      |                      |         | $\checkmark$ |      |                  |                       |                        |             |  |  |
| Measurements/f                      | ield tests:          |         |              |      | $\checkmark$     | Please refer          | to attachment for de   | etails      |  |  |
|                                     |                      |         |              |      |                  |                       |                        |             |  |  |

General observation:

Reservation: 1) Style SHERBA: Found color GRY GEO and Electric blue (60%), color black (30%) with sharp points on plastic stopper at hem and top of placket.

2) Style HUDSON and CUTTER with high proportion defective samples at Velcro tape of placket.

3) Style MAPLE: found pocket width is 18cm while spec is 20cm of all size, while finding pocket height including flap is 20cm.

## OVERALL INSPECTION CONCLUSION: CONFORM Ø NOT CONFORM (AQL, Measurement & Reservations)

Follow up action: (as applicable)

() Inspection certified will be issued after client's confirmation/ approval for reservations.

() Additional services: () Loading supervision(After Principle's approval () Stuffing supervision () Testing () others\_\_\_\_\_

# Samples drawn by:

| For Lab testing: | For record: | For Client: | Sealed at factory: | Or reason for not taking |
|------------------|-------------|-------------|--------------------|--------------------------|
| samples:         |             |             |                    |                          |



Suite 1601-2 Kowloon Plaza, 485-Castle Peak Road, Kowloon, HONG KONG Tel: +852-2724-4786 Fax: +852-2721-5786 info@asiatextileinspections.com www.asiatextileinspections.com

| D (   |  |
|-------|--|
| Date  |  |
| Date. |  |

Report Number:

Page 2 of 5

### **INSPECTION METHOD APPLIED:**

ANSI / ASQC Z1.4-1993, Single sampling plan Or:: AQL 2.5/4.0 LEVEL II

Acceptable Quality Level(AQL) for: Critical: <u>0</u> Major: <u>10</u> Minor: <u>14</u> Sample size: <u>200 PCS</u>

Sample Selection formula: Square root basis No. of Cartons Selected: 22 CTNS

#### Samples selected from package numbers : <u>MAPLE :2,9,17; VUITTION: 2,9; AVENUE: 3,6,9,14; SHERBA (USA): 2,</u> (CANADA): 6,(UK-AF): 9,(UK-MAIN): 7,36,47,60; HUDSON (UK-AF): 2, (UK-MAIN) 1,4; CUTTER (UK-AF): 4, (UK-MAIN): 3,10. 1. PRODUCT CONFORMITY:

| 1.1 Style Conformity:     | yes            | 🗌 no | $\ensuremath{\boxtimes}$ no reference sample / specification available |
|---------------------------|----------------|------|--|
| 1.2 Material Conformity:  | ⊡yes           | 🗌 no | $\ensuremath{\boxtimes}$ no reference sample / specification available |
| 1.3 Color Conformity:     | □yes           | 🗌 no | $\ensuremath{\boxdot}$ no reference sample / specification available   |
| Reference sample provided |                |      |  |
|                           | From principal |      | from manufacturer  |
|                           | From supplier  |      | $\boxdot$ not available (explanation if necessary )                    |



Suite 1601-2 Kowloon Plaza, 485-Castle Peak Road, Kowloon, HONG KONG Tel: +852-2724-4786 Fax: +852-2721-5786 info@asiatextileinspections.com www.asiatextileinspections.com

Date:

Report Number:

Page 3 of 5

## 2. WORKMANSHIP APPEARANCE / FUNCTION INSPECTION FINDINGS:

| Defective samples            | Critical | Major | Minor |
|------------------------------|----------|-------|-------|
| Style MAPLE (S/S 9PCS)       |          |       |       |
| Scars/beside armhole         |          | 01    |       |
| Style BUITTON(S/S 5PCS)      |          |       |       |
| Scar/inside placket          |          |       | 01    |
| Style SHERBA (S/S 116pcs)    |          |       |       |
| Broken stitches              |          | 01    |       |
| Pleat                        |          | 01    | 01    |
| Additional stitches          |          | 01    |       |
| Uncut thread end             |          |       | 02    |
| Poor joining stitches        |          |       | 01    |
| Style AVENUE (S/S 27pcs)     |          |       |       |
| Puckering                    |          | 01    |       |
| Poor joining stitches        |          |       | 01    |
| Uncut thread end             |          |       | 01    |
| pleat                        |          |       | 01    |
| Style HUDSON (S/S 12pcs)     |          |       |       |
| Broken stitches/Velcro tape  |          | 01    |       |
| Missed stitches/Velcro tape  |          | 01    |       |
| Poor joining stitches        |          | 01    |       |
| Uncut thread end             |          |       | 01    |
| Style CUTTER (S/S 31pcs)     |          |       |       |
| Missed stitches/Velcro tape  |          | 01    |       |
| Run off stitches/Velcro tape |          | 01    |       |
| Slant main label             |          | 01    |       |
| Poor joining stitches        |          |       | 01    |
| Total Defectives :           |          | 11    | 10    |
| Maximum allowed :            |          | 10    | 14    |

| Critical defective maximum allowed |    |
|------------------------------------|----|
| Major defective maximum allowed    | 10 |
| Minor defective maximum allowed    | 14 |

☐ Within AQL☐ Within AQL☑ Within AQL

Found Found <u>11</u> Found <u>10</u> □ beyond AQL
☑ beyond AQL
□ beyond AQL

Reservation:

1) Style SHERBA: found color GRY GEO and Electric blue (60%), color black (30%) with sharp points on plastic stopper at hem and top of placket for this shipment.



Suite 1601-2 Kowloon Plaza, 485-Castle Peak Road, Kowloon, HONG KONG Tel: +852-2724-4786 Fax: +852-2721-5786 info@asiatextileinspections.com www.asiatextileinspections.com

Date:

Report Number:

Page 4 of 5

## 3. PRODUCT-SPECIFIC CHECKS ON REDUCED SAMPLE SIZE (as applicable for specific product / order)

Size measurement on <u>59</u> sub-samples: yes

⊠ no

actual finding

| Measurement Point | Size | Ref. Sample | Spec. | Tolerance | <b>Deviation/ Finding</b> | Sample(s) |
|-------------------|------|-------------|-------|-----------|---------------------------|-----------|
|                   |      |             |       |           |                           |           |

### 4. PACKING:

| Style MAPLE/VUITTON :each piece in      | n fold pacl | ked with tis        | ssue paper inserted and back, a small silica gel in each pocket         |
|---|-------------|---------------------|---|
| Then put into an individual polybag s   | ealed by g  | jummed ta           | pes ;solid color and size in a master poly-bag per carton with          |
| a card on top and bottom. Other style   | :each pie   | <u>ce in fold p</u> | acked with a tissue paper on back then put into an adhesive po          |
| solid color and size per. Per carton wi | th on top a | and bottom          | <u>L</u>  |
|   |             |                     |   |
| 4.1. Individual packing Conformity:     | ⊠ yes       | 🗌 no                | ()  |
|   |             | _                   |   |
| 4.2. Inner packing conformity:          | ⊠ yes       | 🗌 no                | ( )   |
| 4.3. Export packing conformity          | ⊠ yes       | no                  | 3-ply corrugated cardboard export carton sealed by transparent tapes () |

4.4. Packing assortment Checked on 22 cartons. found correct

| Carton No. | Size/ Style | Color | Deviation(+ / - samples) |
|------------|-------------|-------|--------------------------|
|            |             |       |                          |

### 5. MARKING / LABEL :

### Actual shipping Marks(if shipping marks not provided in advance) Please refer to photos for details

| 5.1. Bar code conformity       | ⊠ yes | no   | On hangtag and barcode card  | () |
|--------------------------------|-------|------|------------------------------|----|
| 5.2. Shipping mark conformity: | ⊠ yes | no   | Printing on two long sides   | () |
| 5.3. Other marks:              | 🗌 yes | ⊠ no |                              | () |
| 5.3.1 Side mark conformity:    | ⊡yes  | no   | printing on two short side ( | )  |
| 5.3.2 Main label:              | ⊡yes  | no   |                              | () |
| 5.3.3 Care label:              | ⊡yes  | no   |                              | () |
| 5.3.4 Composition label:       | ⊡yes  | no   |                              | () |
| 5.3.5 Size label               | ⊡yes  | no   |                              | () |
| 5.3.6 Country origin label:    | 🗌 yes | ⊠ no |                              | () |



Suite 1601-2 Kowloon Plaza, 485-Castle Peak Road, Kowloon, HONG KONG Tel: +852-2724-4786 Fax: +852-2721-5786 info@asiatextileinspections.com www.asiatextileinspections.com

| Date:  | Re       | port Number: |                         | Page 5 of 5               |
|--|----------|--------------|-------------------------|---------------------------|
| 5.3.7 Hangtag:                                       | ⊠ yes    | 🗌 no 🛛       |                         | ( )                       |
| 5.3.8 Poly-bag printing/ label:                      | ⊠ yes    | 🗌 no 🛛       |                         | ( )                       |
| 5.3.9 Inner box printing / label:                    | □yes     | ⊠ no         |                         | ( )                       |
| 5.3.10 Other Label                                   | ⊠ yes    | no           | lecorate label please s | see photos for details () |
| 6.0 INFORMATIVE OBSERVATI<br>Inspection Environment: | ONS:     |              |                         |                           |
| Lighting:  | 🗌 Daylig | ht           | ☑ Room lighting         | ☑ Sufficient              |
| Inspection place:                                    | ⊡Factory | v workshop:  | Warehouse               | Others :                  |
| Inspection done on:                                  | ☑ Table  |              | Top of cartons          | Others :                  |
| Cleanliness:   | ☑ Clean  |              | Dirty                   | Others :                  |
| Weather condition:                                   | 🗌 Rainy  |              | ☑ Dry                   | Others :                  |
| 7. LOADING SUPERVISION:                              |          |              |                         |                           |
| Performed on   | Sch      | edule for    |                         | Not required              |
| Seal no.:  |          |              |                         |                           |

8. ATTACHMENTS: Photo report.